




	·					FIRE EXIT	FIRE EXIT
6.7 m	SERVIC	E CORNIJOR	s-RVICE COHRIJOR 2.4 m	2.4 m	2.4 m	4.2 m	
T T T					·····		
I21	I50 I51 3mx3m 3mx3m 3	I52 I53 I54 mx3m 3mx3m 3mx3n	1 155	I56 I57	 		
I20							
imx3m							
I19 <sup>⊠</sup> mx3m	I49 I48 3mx3m 3mx3m 3	I47 I46 I43 mx3m 3mx3m 3mx3n	5 I44 I43 1 3mx3m 3mx3m	I42 I41 3mx3m 3mx3m	I40 I39 I38 3mx3m 3mx3m 3mx3m	I37 I36 3mx3m 3mx3m	CAFETERIA 17m X 11m
I18	I22 I23	I24 I25 I20	6 I27 I28	I29 I30	I31 I32 I33	I34 I35	187 SQM
mx3m	3mx3m 3mx3m 3	mx3m 3mx3m 3mx3n	a 3mx3m 3mx3m	3mx3m 3mx3m	3mx3m 3mx3m 3mx3m	3mx3m 3mx3m	
I17 mx3m							
I16	H19 H20		H22 H23	H24	H25 H26	H27	
I15	5m x 3m 5m	1 x 3m 5m x 3m H17 H16	5m x 3m 5m x H15 H14		5m x 3m 5m x 3m H12 H11		
mx3m	5m x 3m	5m x 3m	H15 5m x 3m 5m 3		5m x 3m 5m x 3m		
I14 mx3m		x 3m				5m x 3m	
I13	H1 H2	H3	H4 H5	H6	H7 H8	H9 G1	7m X 9m
mx3m		x 3m 5m x 3m		x 3m 5m x 3m	5m x 3m 5m x 3m	Emp v 2mp	
I12 mx3m	F1 F2		F4 F5	F6	F7 F8	F9	ORG. OFFICE
I11	5m x 5m 5m	n x 5m   5m x 5m	5m x 5m 5m	x 5m   5m x 5m	5m x 5m 5m x 5m	i 5m x 5m	7m x 5m
mx3m I10 <sup>⊴</sup>							E4
mx3m							7m x 5m
I9 mx3m	D12 8m x 4.5m	D11 8m x 4.5m	D10 8m x 4.5r	D9 n 8m x 4.5	D8 m 8m x 4.5m	D7 8m x 4.5m	
18							E3 7m x 5m
mx3m	D1 8m x 4.5m	D2 8m x 4.5m	D3 8m x 4.5n	D4 n 8m x 4.5	D5 m 8m x 4.5m	D6 8m x 4.5m	
I7 <sup>⊴</sup> mx3m						01174.011	E2
16							7m x 5m
imx3m							E1
I5 Bmx3m	B1	B2	B3	B4	B5	B6	7m x 5m
I4 <sup>⊴</sup> mx3m	9mx8m	9mx8m	9mx8m	9mx8m	9mx8m	0	
I3	9111X0111	9112011	SILIXOIN	SUIXOU	9112011	9mx8m	A1
Bmx3m							SPONSOR



**Managed By** 



1st Floor, Sojat Bhavan, 342, Kalbadevi Road, Mumbai - 400 002. Contact : 022 : 22061775 / 2101 / 40162101. Mobile : +91 8779410501 Email : hindustanchamber@gmail.com Website : www.hccmumbai.com

